

NEW

MEASURING **WITHOUT** SAMPLE PREPARATION



promex CT

NEW

»» high-end computed tomography



Measuring area in \varnothing

115 mm

Sample preparation



Measuring accuracy

$\pm 10 \mu\text{m}$

Measuring time

150 s

Multi measurements



- > Valuable time savings
- > Operator-independent quality control
- > Reliable measuring results
- > Easy and intuitive handling
- > Valuable financial and material savings
- > Measuring of very small, thin-walled and complex profiles



CONTACT US

